


 18-5303 AP# 865 CONTACT SET	 18-5345 AP# 864 CONDENSER	 18-5407 AP# 866 ROTOR
---	--	---

PARTS FOR CONTACT CONTROLLED DISTRIBUTORS

Year	Cyl.	Model or Engine	Distributor	Sierra Contact Set	Sierra Condenser	Sierra Rotor
1979	8	ALL	IBM-7010	—	18-5345	18-5407
			IBM-7011	18-5303	18-5345	18-5407

 18-5268 TUNE-UP KIT	 18-5271 TUNE-UP KIT	 18-5275 TUNE-UP KIT
---	---	--

 18-5276 TUNE-UP KIT	 18-5277 TUNE-UP KIT	 18-5280 AP# 3072 TUNE-UP KIT
---	--	--

 18-5278 AP# 3073 TUNE-UP KIT	 18-5281 AP# 3074 TUNE-UP KIT	 18-5283 AP# 3075 TUNE-UP KIT	 18-5279 AP# 3082 TUNE-UP KIT
--	--	--	--

PARTS FOR IGNITION - TUNE-UP KITS

Cyl.	Ignition System	Sierra Tune-Up Kit	Cyl.	Ignition System	Sierra Tune-Up Kit
In-Line 4	Delco Single Point	18-5268	In-Line 4	Delco EST	18-5280
V-8	Mallory Single Point	18-5271	V-6	Delco EST	18-5278
V-8	Prestolite Single Point - Screw Down Cap	18-5275	V-8	Delco EST	18-5281
V-6	Prestolite Single Point - Screw Down Cap	18-5276	In-Line 4	Mallory Single Point	18-5283
V-8	Prestolite Single Point - Clip Down Cap	18-5277	V-8	Prestolite Electronic	18-5279


INBOARD

INDMAR

Ignition/Gaskets




**18-5434
COIL**




**18-5450
RESISTOR**

COIL AND RESISTOR

Year	Model or Engine	Service Coil	Resistor
1979	12 VOLT W/ 2 PRONG RESISTOR	18-5434	18-5450



**18-0603
GASKET SET**




**18-0604
AP# 1808
GASKET SET**




**18-1200
4" ELBOW TO
MANIFOLD GASKET**



**18-3304
NEOPRENE IMPELLER**
Replaces: Johnson Pump 09-802-B
Dia: 3 3/4" Side Width 3 1/2"



**18-0665
AP# 1742
THERMOSTAT GASKET**
Re: 98-5006



**18-0476
BLOCKOFF GASKET**
Re: Barr 1-0105

MISCELLANEOUS GASKETS

Model or Engine	Sierra Gasket Set
Ford 302/ 350 CID Engines	18-0603
GM 305/350 CID Engines	18-0604

MISCELLANEOUS GASKETS

Type	O.E. #	Sierra Gasket
4" Elbow to Manifold	—	18-1200
Thermostat	98-5006	18-0665
Block Off For: Small block GM & Ford V-8 (Use with 18-1999/AP#5705 Manifold)	Barr 1-0105	18-0476

INBOARD



18-3586
AP# 2282
RAW WATER PUMP
Replaces: Indmar 685011
For Impeller Repair Kit use **18-3081**



18-3587
AP# 2283
RAW WATER PUMP
Replaces: Indmar 685001
For Impeller Repair Kit use **18-3089/AP#13150**

MARINE POWER

PKG. OF 2



18-0476
1869
BLOCK-OFF GASKET
Re: Barr 1-0105

PKG. OF 2



18-2909
EXHAUST MANIFOLD GASKET
For: GMV-6



18-8536
5417
MOUNTING KIT



18-8535
5605
MOUNTING KIT


EXHAUST MANIFOLD HARDWARE MOUNTING KITS

Sierra Exhaust Manifold	AP Exhaust Manifold	Elbow O.E. #	Sierra	AP KIT
18-1997-1	5517	Barr CHV-1-83 Indmar 53-1027 Marine Power 0994-000	18-8536 18-8536 18-8536	5417 5417 5417

EXHAUST ELBOW HARDWARE MOUNTING KITS

Sierra Exhaust Elbow	AP Exhaust Elbow	Elbow O.E. #	Sierra Kit	AP Kit
18-1999	5705	Barr 20-0082	18-8535	5605
—	5727	Barr 20-0100	18-8535	5605

PERKINS MARINE ENGINE



18-5975
Alternator
Replaces: Perkins 2871A651
Valeo 2939590
Motorola 9AR3959G, 3855G, 6000G,
510-845, -860, -864
(28 Volt 45 AMP)
For Perkins Marine Engine: 6-354-4, SAEJ1171